JUN 1 6 2005 35 03500.015664 18 TRADEMARK

PATENT C

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

| In re Patent of: |) | | |
|-------------------------------|----------|------------------------|---------------|
| | • | Examiner: Hoan H. Tran | |
| HIDEKAZU SHIMOMURA ET AL. |) | | |
| | : | : Group Art Unit: 2852 | |
| Appl. No.: 09/922,643 |) | | |
| Filed, August 7, 2001 | : | Confirmation No | o.: 9259 |
| Filed: August 7, 2001 |) | | |
| For: IMAGE SENSING DEVICE |) | | Certificate |
| U.S. Patent No.: 6,873,804 B2 | : | | JUN 2 3 2005 |
| | <i>)</i> | | of Correction |
| Issued: March 29, 2005 | , | June 16, 2005 | of Collection |

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence A. Stahl
Attorney for Patentees
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,873,804 B2

DATED

March 29, 2005

INVENTOR(S) :

HIDEKAZU SHIMOMURA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 51, "by" (1st occurrence) should be deleted.

Line 56, "light" (2nd occurrence) should read --light,--.

COLUMN 2:

Line 2, "to be" should read -- can be--.

COLUMN 6:

Line 42, "diagram" should read --diagrams--.

Line 58, "showing" should read --showing on--.

COLUMN 7:

Line 49, "cartridges" should read --cartridge--.

COLUMN 9:

Line 33, "61. Part" should read --61, part--.

COLUMN 10:

Line 28, "to be" should read --be--.

COLUMN 14:

Line 12, "34aand" should read --34a and--.

Line 29, "magnification 1μ1." should read --magnification 1β1.--.

Line 56, "is .10" should read --at 1.0--.

COLUMN 16:

Line 29, " $4=X^2+Y^2$ (1-2)" should read $-4=\sqrt{X^2+Y^2}$ (1-2)--.

Line 42, "surface" should read --surface can--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

JUN 2 3 2005

PATENT NO. 6,873,804 B2

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,873,804 B2

DATED

March 29, 2005

INVENTOR(S) :

HIDEKAZU SHIMOMURA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 11, "being" should be deleted.

Line 24, "such as" should read --such a--.

COLUMN 19:

Line 29, "forming," should read --forming--.

COLUMN 20:

Line 7, "according" should read --according to--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>6,873,804 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30)

JUN 2 3 2005